#### Meagan Redfern

From:

OCARS Pro@uncc.org

Sent:

Monday, May 02, 2005 1:48 PM

To:

Meagan Redfern

Subject:

UNCC EMLCFM 2005/05/02 #00278 A0187434-00A NORM NEW

Phone: (303)487-0377

City:

**SDMS Document ID** 

EMLCFM 00278 UNCCa 05/02/05 01:47 PM A0187434-00A NORM NEW STRT LREQ

Ticket Nbr: A0187434-00A

Original Call Date: 05/02/05 Time: 01:47 PM

Op: MRE Locate By Date : 05/04/05 Time: 11:59 PM Meet: N Extended job: N

State: CO County: DENVER

Addr: 3718 Street: RACE ST

Grids: 03S068W23SE : 03S068W26NE

Lat/Long: 39.769981/-104.964295 39.769981/-104.962513

: 39.767499/-104.964295 39.767499/-104.962513

Type of Work: SOIL EXCAVATION

Boring: N

Location: LOC ENTIRE LOT\*TO INCLUDE ALL CITY PROPERTY FROM CURB TO PROPERTY

Company: PROJECT RESOURCES INC.

Caller : MEAGAN REDFERN

Alt Cont: AMY JAMES

Phone: (303)487-0377

Email: MREDFERN@PROJECTRESOURCESING.COM

Done for: EPA/ARMY CORPS OF ENGINEERS

Remarks:

Members 360NT3 = 360 NETWORK-TOUCH AMERICA

CMSND00= COMCAST - NORTH

Type: OTHR

Members ICGTL3 = ICG TELECOMMUNICATIONS

PCNDU0 = XCEL ENERGY-NORTH

Exp.: N

Legal: Y

DENVER

Members PSND14 = XCEL ENGY--APPT SCHEDULE-- U QLNCND0= QWEST LOCAL

NETWORK (UQ)

Members QLNCND1= QWEST LOCAL NETWORK

SPRN01 = U.S. SPRINT

Members TWTEL1 = TIME WARNER TELECOM WCG01 = WILTEL

COMMUNICATION

You are responsible for contacting any other utilities that are not listed above

including the following tier 2 members not notified by the center:

DNVH20 DENVER WATER DEPT

(303) 628-6666

DNVPR1 DENVER PARKS & REC.

(303)458-4839

DTEO01 DNVR TRAFFIC ENG OPERAT. WWMG01 WASTEWATER MGMT DIVISION

(720)865-4001 (303) 446-3744

3 Mic / 4/13/12 sod 5hcd 1800 Dispose not replace 1 leave 75 cc remove poles and 50 d Clothline leave for owner Poles 14X 54 O Leave 527 can propose of any concrette and not I 50(! 3718 MACK 560 54×5 Lacia Previewed be 508 remov C pispist of sod Bush 500 15×20 500 10× 24 sod o H20 meter 64 32X7 50 d 32×16 5/2 sod 50 d

10

Project Resources Inc.

## **Property Completion Agreement**

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

<del></del>	
Property ID: 896	
Property Address: 3718 RACE ST.	
Owner: CHARMAINE : MARK GARLIA	
Phone: W-3) 861-214 GT. 2431/CEU 3	<del>\437-8777</del>
	946-6479
estoration Items in Question:	, , , , , , , , , , , , , , , , , , , ,
item:	
tem:	
e	
tem:	
tem:	· · · · · · · · · · · · · · · · · · ·
1	
tem:	
tern:	
additional Comments:	
	···
•	
V	
I agree restoration is completed, except as noted	
I do not agree restoration is completed .	
7	
I agree that the sprinkler system is working properly following reinstallation by contractor	
1 15 5 -	7-15
COUNTY CELLINAL	actor's Signature Date





## U.S. Environmental Protection Agency Vasquez Boulevard I/70 Superfund Site Replacement Certificate

Property Owner	Charmaine and Mark Garcia
Property Address	3718 Race Street
Property Identification Number	896

Material Removed	Quantity	Unit Price	Replacement Value
Flower bed area (square feet)			
Trees	1	\$50.00	\$50.00
Itemized shrubs/bushes	1	\$12.00	\$12.00
Total			\$62.00

The acceptance of the replacement certificate and the signature below is full acknowledgement by the property owner that this is a fair and reasonable compensation for plant materials removed during remediation activities, but not planted or installed by the government or it's contractors.

The total amount of \$62.00 has been received by the owner in the form of a replacement certificate, #15634, to be utilized at Paulino's Gardens, 6300 N. Broadway, Denver, CO 80216.

Property Owner's Signature

Date

Contractor's Signature

Date





- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc;
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

#### AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact the VB/I-70 Command Center at (303) 487-0377.

I grant access to my properties		☐ I do not grant access to my propertie		
Jarma &	Jaca .	Man Garcino	10-20-0	
Signature	Date	Signature	Date <sub>.</sub>	
☐ I would like to be	e present during any samp	oling that is required.		
My property has	a working sprinkler syste	em that will need to be replaced.		
•				
	Page 2	c of 2		



- Remover obstrucciones, incluyendo botes, remolque, vehículos, juguetes de niños, montones de madera, casas de perros, etc.
- Remover bulbos de flores, u otras plantas que el Otorgante o inquilino del Otorgante quisiera guardar;
- Regar y mantener el reemplazo de vegetación, incluyendo la aplicación de fertilizante, subsecuente a la riega inicial por la EPA, a menos que el uso de agua esté restringido por la Junta de Agua de Denver.
- Seguir las recomendaciones de la guía de Salud y Seguridad de la EPA;
- Si la propiedad es rentada, asistir a la EPA a obtener la aprobación del inquilino para tener acceso a la propiedad dende se va a llevar a cabo el trabajo, si acaso la EPA no logra obtener acceso; y
- Permitir a hacer un video y/o tomar fotos de la propiedad, incluyendo el área exterior y interior del edificio.

#### ACUERDO A NO INTERFERIR

El Otorgante está de acuerdo a no interferir o meterse en cualquier actividad o trabajo hecho, o equipo que va a llevar a cabo las actividades en la propiedad, o arriesgar la salud o bienestar de los Cesionarios o el medio ambiente, o permitir otras personas a usar la propiedad en alguna manera.

Si tiene preguntas sobre este programa, por favor llame al centro de comando de VB/I-70 a (303) 487-0377.

Si, yo permito acces	] Si, yo permito acceso a mi propiedad.		eso a mi propiedad.
	-		
Firma	Fecha	Firma	Fecha
	resente durante de cualqu ne un sistema de regar plan	ier colección de muestras. ntas y sacate (sprinkler syste	em).
	Página 2	of?	

3718 Race # 896

## **Property Check-List**

#### Yes/No

1. No Sprinkler System?

2. Basement Photos?

3. Photos of Water Meter?

4. All 3 Signatures?

5. 5 Number of Trees?

6. Approximate Voucher Size?

7. Are all trees and bushes clearly labeled on the map?

8. Clotheslines marked and is it removed or replaced?

9. House accessible for equipment?

10. Owner clear of everything they will need to remove?

11. Owner clear the dates when we call him are approximate?

12. A second walk through done on the property to double check the map by the individual who did the video/photos?



# **Property Access Checklist**

Property ID: SQ		ı ==	STARTED ON:/_/_ COMPELTED ON:/_/_
Property Address: 3718 Race 5+.		☐ WORK	COMPELTED ON:/_/_
		,	
Property Owner: Charman Mar	K Garcia	Property R	
Mailing Address:		Home Phor	1e:
37-18 Race St.		Fax:	
Home Phones		Cell/Pager:	<u> </u>
Home Phone: 303-861-2111 e	xt. 2431	Additional	Information:
Cell/Pager: 303-437-8777			
Notification Letter	S-+ 10	1 1 101 6	P
<del>[</del>	<del></del>	1 104	By: A. James
Access Agreement	1		By: Chaine Good 9
Restoration Agreement	<del> </del>	18 104	
Topsoil Sampling (if applicable)		_'	By:
Disposal Sampling (if applicable)	'_	_/ By:	
Garden Sampling (if applicable)		_'	By:
Utility Clearance	Called:	_//	By:
Video/Photos (Before)	On: (\)/	8104	By: K. Hughes
☐ Video/Photos (During)	On:/	/	By:
☐ Video/Photos (After)	On:/	/	By:
☐ Video/Photos (30-Day)	On:/	/	Ву:
☐ Property Completion Agreement	Signed:	.//	Ву:
☐ Final Report Issued:		//_	Ву:
Air Monitoring (as applicable)			
	//	By:	
Results:			}
	//	By:	
Results:			
Community Crew On:	11_	By:	
Results:			



### **Restoration Agreement**

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: 896
Property Address: 37/8 CACC
Owner: Charmaine Garcia
Phone:

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

# Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:	
	Any decorative stores
item:	
	Bird both
Item:	
	any other items in yerd
Item:	
item:	
ltem:	
Item:	
Item:	



item:

item:

# Items To Be Removed By Contractor During Remediation And <u>Not Replaced</u> (Use additional sheets as necessary)

I tems marked or map

item:	
Item:	
Item:	
Item:	·
Item:	
	Items To Be Removed By Contractor During Remediation And Replaced (Use additional sheets as necessary)
item:	~10
Item:	1
Item:	
Item:	
Item:	
Item:	·
Item:	



# Landscape Inventory (Use additional sheets as necessary)

ltem	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	27.45	Square Feet	
Number of trees > 2 inch trunk diameter	NIA 5	·	·
Number of trees < 2 inch trunk diameter	١١٥		
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc.  Attach a sketch of the sprinkler layout.	N/A		Zones:
Number of and total size of all gardens / flower beds.	# Of Beds:		Fr <sup>2</sup> Of Beds: <u>ルル</u>
Attach a sketch of relative sizes and locations.	# Of Gardens:		Ft <sup>2</sup> Of Gardens: ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~



# Project Resources Inc.

ltem	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials not to be replaced by contractor.  Note this value will be used to issue a plant voucher to the property owner.	Total # Of Beds:	\$	Total Ft <sup>2</sup> Of Beds To Be Replaced With Certificate:
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed.  Include a sketch of were each plant will be placed by the contractor.		Each	Only Use For Plants That Are Being Saved and Replanted
Agreed upon area of property to be replaced with grass sod.  Include a sketch of the area(s) to be replaced with grass sod.	2201	SF	Total Fr <sup>2</sup> Of Sod To Be Laid: 2713
Area of City or County property to be landscaped per their requirements.  Include a sketch of the area (s)	Total Fr <sup>2</sup> :	SF	Sod:
Agreed upon area of property to be replaced with mulch.	Total Ft <sup>2</sup> Of Mulch:	SF	Red:



# Project Resources Inc.

ltem	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft <sup>2</sup> Of Rock:	SF	Large: NA  Medium: NA  Small (pea gravel): NA  Driveway Gravel: 12
Agreed upon area to be replaced with no groundcover.	Total Ft <sup>2</sup> With No Groundcover:		

	Additional Comments / Instructions:
ĺ	
[	
}	
	·
,	
<b>,</b>	
	·



	Additional Comments / In	structions Continued:	
-			
	,		·
			·
· · · · · · · · · · · · · · · · · · ·			
Check the box if pre-existing damage	Owner does not want PRI to does. By checking this box PRI is	ocument interior founda not responsible for ar	ation walls and possible ny damage done to the
interior of house, inc	luding foundation cracks or fissu	ures.	-
1 agree	I do not agree	🔀 I agree	I do not agree
$\sim$ 1			7
harme a	Laria 12-8-04	Jon )	Mr 12-4-04
Owner's Signature	Date	Contractor's Signatu	e Date





### Real Property Records

Date last updated: Friday, November 26, 2004

### **3** Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

Link to property tax information for this property
Link to property sales information for this neighborhood
Link to property sales information for all Denver neighborhoods

#### PROPERTY INFORMATION

Property Type: Residential

Name and Address Information

GARCIA, CHARMAINE S &

GARCIA.MARK A JR & SHAMIRA C &

**3718 RACE ST** 

**DENVER, CO 80205** 

Parcel: 0226103007000

Legal Description

L 12 & S 10 FT OF L 11 BLK 4 CHEESMAN & MOFFATS ADD

RESIDENTIAL

**DENV** 

**Property Address:** 

Tax District

**3718 RACE ST** 

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	21700	1730		
Improvements	143900	11450		
Total	165600	13180	0	13180
Prior Year				
Land	21700	1730		
Improvements	143900	11450		
Total	165600	13180	0	13180

Style: One Story

Year Built: 1911

Building Sqr. Foot: 866

Bedrooms: 2

Baths Full/Half: 1/0

\_\_\_\_\_\_

Basement/Finished: 970/866

Lot Size: 4,370

Zoning: R2


Reception No.: 0000123316

Recording Date: 10/19/92

Document Type: Quit Claim

Sale Price: 10

Mill Levy: 64.162



					<del></del>
1)	896 -001	500	1415 Lours	6/8/06	1' off set
2)	896 -002	SCC =	1420 hours	6/8/0 6	1' offset
3)	896 -001	DWC	1425 hours	6/8/66	
4)	8% -002	DWC	1430 hours	1/8/05	
5)					
6)					



# 4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample 1D: 896-001-SCC Client Project ID: 213001.01 Date Collected: 6/8/06 Date Received: 6/8/06 Lab Work Order: 06-3650

Lab Sample ID: 06-3650-13

Sample Matrix: Soil

**METALS** 

Method: SW6010 Prep Method: SW3050

Date Prepared: 6/12/06 Lab File ID: 061606PM Dilution Factor:

Date Analyzed: 6/17/06 Method Blank: MB-10126 Lab Fraction ID: 06-3650-13A

 Analytes
 CAS Number
 Result
 LQL
 Units

 Lead
 7439-92-1
 53
 5.4
 mg/Kg

MB Analyst

Approved

\_\_\_\_\_

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

 -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL. Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 6/19/06

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 896-002-SCC Client Project ID: 213001.01 Date Collected: 6/8/06 Date Received: 6/8/06

Lab Work Order: 06-3650 Lab Sample ID: 06-3650-14

Sample Matrix: Soil

**METALS** 

Prep Method: SW3050 Method: SW6010

Date Prepared: 6/12/06 Lab File ID: 061606PM **Dilution Factor:** 

Date Analyzed: 6/17/06 Method Blank: MB-10126 Lab Fraction ID: 06-3650-14A

Analytes **CAS Number** Result LQL Units 7439-92-1 24 5.4 mg/Kg Lead

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Approved

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 896-001-DWC Client Project ID: 213001.01 Date Collected: 6/8/06 Date Received: 6/8/06 Lab Work Order: 06-3650 Lab Sample ID: 06-3650-15 Sample Matrix: Wipe

**METALS** 

Method: SW6010 Prep Method: SW6010

Date Prepared: 6/9/06 Lab File ID: 061206PM Dilution Factor: 1

Date Analyzed: 6/13/06 Method Blank: MB-10113 Lab Fraction ID: 06-3650-15A

 Analytes
 CAS Number
 Result
 LQL
 Units

 Lead
 7439-92-1
 U
 4.0
 μg/WIPE

Analyst

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Approved

**Definitions:** NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 6/19/06

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: 896-002-DWC Client Project ID: 213001.01 Date Collected: 6/8/06 Date Received: 6/8/06

Lab Work Order: 06-3650 Lab Sample ID: 06-3650-16 Sample Matrix: Wipe

**METALS** 

Method: SW6010 Prep Method: SW6010

Date Prepared: 6/9/06 Lab File ID: 061206PM Dilution Factor:
Date Analyzed: 6/13/06 Method Blank: MB-10113 Lab Fraction ID:

Date Analyzed:6/13/06Method Blank:MB-10113Lab Fraction ID:06-3650-16AAnalytesCAS NumberResultLQLUnits

Lead 7439-92-1 U 4.0 μg/WIPE

MA

Approved

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

 -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL. **Definitions:** NA - Not Applicable

LQL - Lower Quantitation Limit


Surr - Surrogate

Print Date: 6/19/06

This spreadsheet performs screening level calculations to estimate the effect of peeling leaded paint on the average concentration of lead in yard soil 3718 Race St.

INPUTS	Variable	Units	House	Garage
General	Mixing depth in yard	cm	2.54	2.54
	Mixing depth in yard	inches	1	1
	Soil density	g/cm3	2.5	2.5
	RBC in soil	mg/kg	400	400
	Bkg in clean fill	mg/kg	50	50
			Small	Small
House-specific	Area of the exposure unit	m2	93.64626	54 626988
	Area of the exposure unit	ft2	1008	588
	Concentration of lead in paint	mg/cm2	38	26
	Area of peeling paint	m2	63,38682	1.129701
	Area of peeling paint	ft2	682.29	12.16
COMPUTATIONS	•			
	Mass of lead from paint	mg	2.4E+07	2.9E+05
	Volume of soil	cm3	2.4E+06	1.4E+06
	Mass of soil	kg	5.9E+03	3.5E+03
	Incremental concentration	mg/kg	4050.6	84.7
	Maximum acceptable area of p	eeling leaded paint (m2)	5.5	4.7
	Maximum acceptable area of p		58.9	50.2
DECISION			Not OK	OK
COMPUTATIONS	Area of the exposure unit Concentration of lead in paint Area of peeling paint Area of peeling paint  Mass of lead from paint Volume of soil Mass of soil Incremental concentration Maximum acceptable area of p	ft2 mg/cm2 m2 ft2  mg cm3 kg mg/kg seeling leaded paint (m2)	1008 38 63 36682 682 29 2.4E+07 2.4E+06 5.9E+03 4050.6 5.5 58.9	588 26 1.129701 12.16 2.9E+05 1.4E+06 3.5E+03 84.7 4.7 50.2

ldress:	3718 Race St.				8/10/2005			
νη <sub>эς:</sub>	Charmaine and Mark	Gar	cia		Telephone #:	( 303) 86	1-2111	
ot Plan:					<del></del>	<del></del>		
•								
	•							
						٠		
		•						
						Ro	1, Ly	2
	•					<i>V</i> *	896	
				ı			896	
			see attached	)			0 0	
							•	
. <del></del>		Exterior Wa	ılls			Doors/	rim	
	Material	deteriorated	·	XRF (Lead)	Material	deteriorated		XRF (Lead
	Material wood		·	XRF (Lead) 38+-11	Material			XRF (Lead
South	wood	deteriorated Area 66.00	·	38+-11	Material	deteriorated		XRF (Lead)
South East		deteriorated Area	·	XRF (Lead) 38+-11 38+-11	Material	deteriorated		XRF (Lead
South East	wood	deteriorated Area 66.00	·	38+-11	Material Total	deteriorated		XRF (Lead)
South East	wood wood Total	deteriorated Area 66.00 96.00	Peel/Chip	38+-11		deteriorated Area	Peel/Chip	XRF (Lead)
South East	wood wood Total	deteriorated Area 66.00 96.00 162.00 v Trim/Fascia	Peel/Chip	38+-11		deteriorated Area  0.00  Patios/Decks	Peel/Chip	XRF (Lead
South East	wood wood Total	deteriorated Area 66.00 96.00 162.00 w Trim/Fascia deteriorated	Peel/Chip /Soffit/gable	38+-11	Total	deteriorated Area	Peel/Chip	
South East West	wood wood Total Windov	deteriorated Area 66.00 96.00 162.00 v Trim/Fascia. deteriorated Area 65.77	Peel/Chip /Soffit/gable Peel/Chip	38+-11 38+-11 XRF (Lead) 21+-7.8		0.00 Patios/Decks	Peel/Chip	
South East West North South	wood  Total  Windov  Material  wood  wood	deteriorated Area 66.00 96.00 162.00 V Trim/Fascia deteriorated Area 65.77 77.62	Peel/Chip /Soffit/gable Peel/Chip	38+-11 38+-11 XRF (Lead) 21+-7.8 21+-7.8	Total	0.00 Patios/Decks	Peel/Chip	
South East West  North South East	wood  Total  Windov  Material  wood  wood  wood	deteriorated Area 66.00 96.00 162.00 V Trim/Fascial deteriorated Area 65.77 77.62 216.67	Peel/Chip /Soffit/gable Peel/Chip	38+-11 38+-11 XRF (Lead) 21+-7.8 21+-7.8 38+-11	Total Material	0.00 Patios/Decksdeteriorated Area	Peel/Chip s/Porches Peel/Chip	XRF (Lead
South East West  North South East	wood  Total  Windov  Material  wood  wood  wood  wood  wood	deteriorated Area 66.00 96.00 162.00 v Trim/Fascia deteriorated Area 65.77 77.62 216.67 72.39	Peel/Chip /Soffit/gable Peel/Chip	38+-11 38+-11 XRF (Lead) 21+-7.8 21+-7.8	Total  Material  wood	0.00 Patios/Decks deteriorated Area	Peel/Chip	
South East West  North South East	wood  Total  Windov  Material  wood  wood  wood  wood  Total	deteriorated Area 66.00 96.00 162.00 v Trim/Fascia deteriorated Area 65.77 77.62 216.67 72.39 432.45	Peel/Chip /Soffit/gable Peel/Chip	38+-11 38+-11 XRF (Lead) 21+-7.8 21+-7.8 38+-11	Total  Material  wood  Total	0.00 Patios/Decks deteriorated Area  87.84	Peel/Chip	XRF (Lead
South East West  North South East	wood  Total  Windov  Material  wood  wood  wood  wood  Total	deteriorated Area 66.00 96.00 162.00 V Trim/Fascia deteriorated Area 65.77 77.62 216.67 72.39 432.45 Trim/Gutters/L	Peel/Chip /Soffit/gable Peel/Chip	38+-11 38+-11 XRF (Lead) 21+-7.8 21+-7.8 38+-11	Total  Material  wood  Total	0.00 Patios/Decks deteriorated Area  87.84 87.84	Peel/Chip s/Porches Peel/Chip	XRF (Lead
South East West  North South East	wood  Total  Windov  Material  wood  wood  wood  Total  Total	deteriorated Area 66.00 96.00 162.00  Varim/Fascia deteriorated Area 65.77 77.62 216.67 72.39 432.45  Trim/Gutters/E deteriorated	Peel/Chip /Soffit/gable Peel/Chip	38+-11 38+-11 XRF (Lead) 21+-7.8 21+-7.8 38+-11 21+-7.8	Total  Material  wood  Total  Misc	0.00 Patios/Decks deteriorated Area  87.84 87.84 Structures/Cdeteriorated	Peel/Chip s/Porches Peel/Chip	XRF (Lead
South East West North South East West	wood  Total  Windov  Material  wood  wood  wood  wood  Total	deteriorated Area 66.00 96.00 162.00 V Trim/Fascia deteriorated Area 65.77 77.62 216.67 72.39 432.45 Trim/Gutters/L	Peel/Chip /Soffit/gable Peel/Chip	38+-11 38+-11 XRF (Lead) 21+-7.8 21+-7.8 38+-11	Total  Material  wood  Total	0.00 Patios/Decks deteriorated Area  87.84 87.84	Peel/Chip s/Porches Peel/Chip	XRF (Lead
South East West  North South East West	wood  Total  Windov  Material  wood  wood  wood  Total  Total	deteriorated Area 66.00 96.00 162.00  Varim/Fascia deteriorated Area 65.77 77.62 216.67 72.39 432.45  Trim/Gutters/E deteriorated	Peel/Chip /Soffit/gable Peel/Chip	38+-11 38+-11 XRF (Lead) 21+-7.8 21+-7.8 38+-11 21+-7.8	Total  Material  wood  Total  Misc	0.00 Patios/Decks deteriorated Area  87.84 87.84 Structures/Cdeteriorated	Peel/Chip s/Porches Peel/Chip Garage/Fen Peel/Chip	XRF (Lead
South East West North South East West	wood  Total  Windov  Material  wood  wood  wood  Total  Total	deteriorated Area 66.00 96.00 162.00  Varim/Fascia deteriorated Area 65.77 77.62 216.67 72.39 432.45  Trim/Gutters/E deteriorated	Peel/Chip /Soffit/gable Peel/Chip	38+-11 38+-11 XRF (Lead) 21+-7.8 21+-7.8 38+-11 21+-7.8	Total  Material  wood  Total  Misc	0.00 Patios/Decks deteriorated Area  87.84 87.84 Structures/Cdeteriorated Area	Peel/Chip s/Porches Peel/Chip Garage/Fen Peel/Chip	XRF (Lead
North South East West North South East West	wood  Total  Windov  Material  wood  wood  wood  Total  Total	deteriorated Area 66.00 96.00 162.00  Varim/Fascia deteriorated Area 65.77 77.62 216.67 72.39 432.45  Trim/Gutters/E deteriorated	Peel/Chip /Soffit/gable Peel/Chip	38+-11 38+-11 XRF (Lead) 21+-7.8 21+-7.8 38+-11 21+-7.8	Total  Material  wood  Total  Misc	0.00 Patios/Decks deteriorated Area  87.84 87.84 Structures/Cdeteriorated Area	Peel/Chip s/Porches Peel/Chip Garage/Fen Peel/Chip	XRF (Lead



 $N \leftarrow$ 

3718 RACE

3718 Race St.		Structure:	House			1	1				
8/10/2005		Direction:	West	T					1		
CM & WH MW								<del>                                     </del>			
11:00 a.m.		<del>                                     </del>	<u> </u>					T		1	
	Photo				Total Area of Element	Percent	Deteriorated Area (units		VDE V-I		
Drawing Number	Number	Painted Surface	Material	Color	(units ft^2)	Deteriorated	ft^2)	XRF#	XRF Value	pos/neg	Notes
		Front Porch			İ					Į.	,
		downspout &			40.07			477	0.00.004		1
		gutter	Metal	Beige	16.67	n/a	n/a	177	0.39±0.21	Neg	
		front porch						1.74	0.07.0.40	l	
		capstones (2)	Stone	Brown	7.50	100%	7.50	171	0.07±0.16		
1	1		Wood	Beige	34.67	100%	34.67	See 172	21±7.8	Pos.	<del></del>
	_	Front Porch				140004	50.47	170	04.75	_	1
2	2	Beams	Wood	Beige	53.17	100%	53.17	172	21±7.8	Pos.	<u> </u>
		Front Porch		_							
		Railing	Stone	Brown	6.25	50%	3.13	See 171	0.07±0.16	Neg.	1
_	_	Front window	ĺ		!	1				_	
3	3	Frame & sash	Wood	Beige	n/a	n/a	0.39	173	2.7±0.9	Pos.	-
	1	Soffit/fascia/							!		
4	:4	dormer trim & walls	Wood	Beige	72.00	100%	72.00	See 172	21±7.8	Pos.	1
	1	1	1	1. 5	1		•				· · · · · · · · · · · · · · · · · · ·
3718 Race St.	1	Structure:	House			ſ				İ	
8/10/2005	<del></del>	Direction:	South						<del>                                     </del>	<u> </u>	1 1
CM & WH MW						1		<u> </u>	1		1
11:00 a.m.						+			<del> </del>	<del></del>	
			1				<del></del>	<del> </del>	<del> </del>	<del> </del>	
		.		†	Total Area		Deteriorated	<del> </del>	<del> </del>	<u> </u>	
	Photo		]		of Element	Percent	Area (units			1	
Drawing Number	Number	Painted Surface	Material	Color	(units ft^2)	Deteriorated	ft^2)	XRF#	XRF Value	pos/nea	Notes
		Lower basement		T		1	† <del></del>	<del>                                     </del>			
5	5	window frames (2)	Wood	Beige	8.83	100%	8.83	See 173	2.7±0.9	Pos.	
)	6	fascia	Wood	Beige	27.75	50%	13.88	172	21±7.8	Pos.	
5		Soffit	Wood	Beige	45.00	100%	45.00		21±7.8	Pos.	<u> </u>
<del></del>	\ <del>-</del>	Window Frames					<del>                                     </del>			† <del></del>	
7	7	(2)	Wood	Beige	3.17	75%	2.38	See 173	2.7±0.9	Pos.	
		Window Frames		-0.30					+		
3	18	(2)	Wood	Beige	6.39	80%	5.11	See 173	2 7+0 9	Pos.	
	<del></del>	Window frame &		20.90		+	<del> </del>		2.7.20.0	<del>                                     </del>	
)	9		Wood	Beige	4.83	50%	2.42	See 173	2.7±0.9	Pos.	1
	<del></del>	gutter	metal	Beige		100%	15.00		0.39±0.21		<u> </u>
	<del></del>	igottei	metal	Deige	113.00	1 100 /6	110.00	1366 111	U.U3±U.4 1	1.4eg.	<del></del>

I<sup>1</sup>

.

•	1	1	1.	1		: 1	1	ı	1		Ψ'
3718 Race St.		Structure:	House				ļ				
8/10/2005		Direction:	East	_				<u> </u>		<u> </u>	
CM & WH MW											
11:00 a.m.											
			İ	İ	Total Area		Deteriorated				
	Photo			İ	of Element	Percent	Area (units				
Drawing Number	Number	Painted Surface	Material	Color	(units ft^2)	Deteriorated	ft^2)	XRF#	XRF Value	pos/neg	Notes
		Window Frame &		1							
10	10	sash	Wood	Beige	4.67_	100%	4.67	See 173	2.7±0.9	Pos.	
		Addition window	}								
11	11	frame & wall	Wood	Beige	96.00	100%	96.00	174	38±11	Pos.	<u> </u>
		Gable end & soffit									
12	12	& fascia	Wood	Beige	212.00	100%	212.00	See 174	38±11	Pos.	1 1
3718 Race St.	İ	Structure:	House	f	l	1	1	1	1	1	1
8/10/2005		Direction:	North	T				† · · · · · ·			
CM & WH MW			1	<u> </u>	1		<del></del>	<u> </u>	1	1	
11:00 a.m.		<del></del>		1		<del> </del>	<del>+</del>	<u> </u>		†	
		<del></del>			Total Area	-	Deteriorated	<b>——</b>	<del> </del>	<del> </del>	
	Photo				of Element	Percent	Area (units	1	!	1	
Drawing Number	Number	Painted Surface	Material	Color	(units ft^2)	Deteriorated	ft^2) `	XRF#	XRF Value	pos/neg	Notes
		Lower basement					<del></del>	<del></del>		1	
13	13	windows (2)	Wood	Beige	5.89	100%	<sup>1</sup> 5.89	See 173	2.7±0.9	Pos.	
14	14	Window frames	Wood	Beige	5.83	100%	5.83	See 173		Pos.	
		Window frames						1			
15	15	smaller (3)	Wood	Beige	4.17	100%	4.17	See 173	2.7±0.9	Pos.	
16	16	Fascia	Wood	Beige	27.75	50%	13.88	See 172	21±7.8	Pos.	
16	16	soffit	Wood	Beige	45.00	80%	36.00	See 172		Pos.	
17	17		Wood	Beige	66.00	100%	66.00	See 174	38±11	Pos.	
		Gutter	Metal	Beige	15.00	100%			0.39±0.21		
3718 Race St.	I	Structure:	Garage	ļ.	1	I		1	1		*** ***
3/10/2005		Direction:	N.S.W.	<del> </del>	<del>                                     </del>	1		<del> </del>	<del> </del>		<del>                                     </del>
CM & WH MW				<del>                                     </del>		<del> </del>	<del></del>	<del></del>	+	<del> </del>	<del>                                     </del>
11:00 a.m.				<del> </del>		<del> </del>	+	<del> </del>	+	<del> </del>	<del>                                     </del>
		<del></del>	<del> </del>	<del> </del>	Total Area	<del> </del>	Deteriorated			·	<del>                                     </del>
	Photo			1	of Element	Percent	Area (units			1	\(\lambda\)
Orawing Number	Number	Painted Surface	Material	Color	(units ft^2)	Deteriorated		XRF#	XRF Value	pos/neg	Notes
8	18		Wood	Green	5.33	100%		175	20±9	Pos.	· · · · · · · · · · · · · · · · · · ·
9	19	Door Frame W.		Green	n/a	n/a	1.50	See 175		Pos.	<del>                                     </del>
•	18	Window Frame S.		Tan	5.33	100%		176		Pos.	<del> </del>

Charmaine 3718 Race St. Denver, Co 80205







VB/I-70 Command Post 10 E. 55th Avenue Denver, CO 80216



# **TARGET SHEET**

# EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1049112

SITE NAME:	VASQUEZ BOULEVARD AND I-70
DOCUMENT DATE:	06/19/2006
Due to one of the fo	DOCUMENT NOT SCANNED ellowing reasons:
☐ PHOTOGRAPHS	<b>,</b>
☐ 3-DIMENSIONAL	-
□ OVERSIZED	
☑ AUDIO/VISUAL	
☐ PERMANENTLY	BOUND DOCUMENTS
☐ POOR LEGIBILIT	ΓΥ
OTHER	
□ NOT AVAILABLE	<b></b>
<b>— </b>	JMENTS NOT TO BE SCANNED , Data Validation, Sampling Data, CBI, Chain of Custody)
DOCUMENT DESCR	RIPTION:
CD - SITE PHOTO	OGRAPHS, PROPERTY #896